

Preliminary Design Review





Team Bumblebee Fall 2020





Arnold Flores

EE496, EE-EP



Francis Sonoda

EE396, EE- EP



Raellis Young

EE496, EE-Systems



Lauryn Corpuz

EE396, EE-EP







- Block Diagrams
 - Power
 - Signal/Communication
- Team Progress
- Problems
- Gantt Chart
- Upcoming Tasks
- Questions

Block Diagram- Power





Block Diagram- Signal/ Communication 55









- Got new members up to speed with Bumblebee
 PCB
- Learned how to solder
- Started populating two Ver. 4.0 boards
- Reviewed Arduino code for XBees
- Reviewed XCTU for XBees to detect each other
- Helped Team Apple with Xbee











Problems





- Ran out of 0.1 uF capacitors
 - Used old capacitors from previous boards
- Range testing (TBD)
 - XBee was unable to detect other XBee's
- Problems with Relay Code
 - Have yet to fix Rx and Tx lines of the relay code
- Waiting for a new board for v4.1
 - Unable to work on v4.1 until then








					TEA	M BUME	BLEBEE								
Fall 2020	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Date	8/31/20	9/7/20	9/14/20	9/21/20	9/28/20	10/5/20	10/12/20	10/19/20	10/26/20	11/2/20	11/9/20	11/16/20	11/23/20	11/30/20	12/7/20
Presentations															
Proposal															
PDR															
CDR															
Final															
Bare Bumblebee															
Build Bare Board															
Test Board															
Relay Testing															
PCB Bumblebee															
Fabricate New Board															
Order New Parts															
Populate															
Test Board															
Relay Testing															
Research															
Raspberry Pi															
WiFi Method															
Reports															
Final Report															
New Plan															
Range Testing															
Documentation															
Research															
Quarantine															




Upcoming Tasks

- v4.0
 - Finish populating
 - o Test v4.0
- v4.1
 - Pick up board from EE office
 - Populate
 - Program
 - Test v4.1
- Conduct more Range Testing
- Fix problems with Relay detection
- Consult Firmware Team
- Need to order parts using Ron Ho Fund
- Update wiki with past presentations





Ver 4.0: 5V Step Up Breakout board



Ver 4.1: 5V regulator SMD (TPS61222DCKR)









