



Cranberry

EE496 Proposal Presentation



Jennifer Chun, Joslyn Hamada, Emily Kane, Emily Lum

Overview



- Introduction
- Cranberry Overview
- Semester Goals
- Learning Expectations
- Team Progress
- Gantt Chart
- Potential Problems





Introduction



Emily Lum

Team Member

- Senior
- Electrical Engineering
 - Electrophysics

Introduction



Emily Kane

Team Member

- Junior
- Electrical Engineering
 - Electrophysics

Introduction



Jennifer Chun

Team Member

- Senior
- Electrical Engineering
 - Electrophysics

Introduction



Joslyn Hamada


Team Member

- Senior
- Electrical Engineering
 - Electrophysics

Cranberry Motivation




- Improve hardware of third generation Cranberry
 - Improve functionality
 - Maintain power consumption and small size
- Fourth generation weatherbox





Cranberry Design Overview

- 2.25" X 2.25" stacked boards
- Top: Sensor Board (4v)
- Bottom: Main Board (4v)
- Sensors:
 - Solar Irradiance, humidity, temperature, pressure
 - Version 4.1: GPS, real time clock
- Housing Design
 - Two main parts: box and panels
 - Mounting piece



Semester Goals



- Finish 2 Cranberry 4.0 and 2 Cranberry 4.1 weatherboxes
 - Populate, test, debug
 - 1 (of each) - Software
 - 1 (of each) - Deploy





Gantt Chart

	1/15	1/22	1/29	2/5	2/12	2/19	2/26	3/5/	3/12	3/19	3/26	4/2	4/9	4/16	4/23	4/30	5/7
Cranberry Update	X	X															
Implement GPS and RTC																	
Solder 2nd Board (4.0)		X	X														
Debug 2nd Board (4.0)																	
Deploy (4.0)																	
Order/Recieve Cranberry 4.1																	
Solder Cranberry 4.1																	
Test and Debug 4.1																	
Deploy (4.1)																	
Final Report																	





Team Progress

- Reviewed board design
- Continued debugging the boards
 - Fixed all the wiring issues on the 2nd set of boards
 - Tested the values
 - Both programmed, confirming values




Learning Expectations



- Improve soldering skills
- Improve debugging skills
- Learn about firmware & testing
- Teamwork



Potential Problems



- More unforeseen issues due to 4.1 board design
- Manually rewiring won't be durable enough





Any
Questions?

